



# La Linea “Earth”

## Drilling table

- ① Drill the holes at the coordinates indicated in the table on page 2 by the X and Y values.
- ② The fixing holes are listed and indicated in page 1 by this symbol: 
- ③ Install the product starting from number 1.



| N° Holes | X    | Y    |
|----------|------|------|
| 1        | 3314 | 0    |
| 2        | 3128 | 559  |
| 3        | 2810 | 1120 |
| 4        | 2461 | 1352 |
| 5        | 1923 | 1358 |
| 6        | 1356 | 1241 |
| 7        | 824  | 1412 |
| 8        | 806  | 1694 |
| 9        | 702  | 1921 |
| 10       | 714  | 2157 |
| 11       | 913  | 2296 |
| 12       | 931  | 2179 |
| 13       | 693  | 2251 |
| 14       | 580  | 2556 |
| 15       | 585  | 2777 |
| 16       | 453  | 2974 |
| 17       | 636  | 2870 |
| 18       | 437  | 2838 |
| 19       | 291  | 2926 |
| 20       | 281  | 3110 |
| 21       | 507  | 3460 |
| 22       | 743  | 3870 |

| N° Holes | X    | Y    |
|----------|------|------|
| 23       | 730  | 4141 |
| 24       | 708  | 4654 |
| 25       | 857  | 5076 |
| 26       | 1026 | 5429 |
| 27       | 590  | 5614 |
| 28       | 133  | 5131 |
| 29       | 0    | 4689 |
| 30       | 263  | 4182 |
| 31       | 1075 | 3846 |
| 32       | 1751 | 3591 |
| 33       | 2137 | 3228 |
| 34       | 1728 | 2508 |
| 35       | 1469 | 1855 |
| 36       | 1760 | 1527 |
| 37       | 2283 | 1563 |
| 38       | 2800 | 1691 |
| 39       | 3172 | 1375 |
| 40       | 3277 | 983  |
| 41       | 3684 | 869  |
| 42       | 4172 | 992  |
| 43       | 4165 | 1406 |